

(438)

## 京浜NO. 3 CGL 操業及び品質向上対策

日本钢管㈱ 京浜製鉄所

広野忠夫 ○安藤嘉紹

伊藤三郎 三島一郎

桑原博司 伊勢保夫

## 1. 緒 言

昭和58年4月に稼働を開始した京浜NO. 3 CGLについて、設備操業結果の一部と、稼働後の製品品質向上対策とその効果について報告する。

## 2. 設備及び品質向上対策の概要

Table 1C, 既設設備（シーラス方式直火加熱炉、亜鉛粉末噴射ミニスパ装置）と、品質向上対策として実施した工事及び新設した設備の概要を示す。品質向上対策の目的は、下記の通りである。

- 炉体N<sub>2</sub>シール…炉内微量O<sub>2</sub>減少、密着性、パウダリング性向上。
- 原板クリーニング設備…原板清浄性向上、めっき表面欠陥防止。
- ストリップ振動防止…ライン高速化、気体絞り操業の安定化。  
(Fig. 1C, 対策、設備の配置を示す。)

## 3. 操業結果

## 1) シーラス方式直火加熱炉

- ストリップの迅速な温度制御可能。還元炉H<sub>2</sub>ガスの低減可能

## 2) 亜鉛粉末噴射ミニスパ装置

- 平滑で均一な外観の達成可能。操業性良好、操業コスト減少

## 4. 品質向上対策の効果

## 1) 炉体シール対策

- 徹底的な炉体シール対策により、炉内O<sub>2</sub>濃度が減少。この結果、めっき密着性、パウダリング性が向上。(Table 2)

## 2) 原板クリーニング設備

- めっき原板表面の、油汚れによる表面欠陥が著しく減少。
- アロイめっき外観均一化。浴中ドロス発生量減少 (Table 2)

## 3) 磁力式振動防止装置

- 気体絞り部でのストリップ振動防止、形状矯正効果により高速時の付着量制御が安定。特に、薄物広幅材に対する効果大。(Table 2)

Table 1 Specification of equipments and improvement

	Specification
Direct fire furnace	Type: Selas (Premix) Fuel consumption: $17 \times 10^4 \text{ Kcal/T}$
Zinc powder spray	Blowing air: $18000 \text{ m}^3/\text{H}$ Powder consumption: $0.08 \text{ kg}/\text{T}$
Sealing of furnace	Sealing parts: Sledding ports Cooling fans e.t.c.
Alkaline Cleaning equipment	Method: Electrolytic Current: $7500 \text{ A MAX}$ Detergent: NaOH
Equipment for preventing strip vibration	Method: attracting and fixing strip edges by magnetic force

Table 2 Results of improvement

	Item	Results
Sealing of furnace	Oxygen concentration	$20 \sim 30 \text{ ppm} \rightarrow 5 \sim 10$
	Adhesion (Poor) 1~5(Good)	$\rightarrow 4.5$
	Powdering (Poor) 1~5(Good)	$\rightarrow 4.5$
	Ratio of Surface defects	$0.1 \rightarrow 0.01$
alkaline cleaning equipment	Generation of dross	$100 \rightarrow 85$
	Max line Speed normally achieved	$160 \text{ mpm} \rightarrow 180$
Equipment for Preventing strip vibration	$\sigma$ of coating weight across strip width	$6.5 \text{ g/m}^2 \rightarrow 4.5$ ( $\bar{x}: 60 \text{ g/m}^2$ )




Fig.1 Layout of equipments and improvement in No. 3 CGL